

AUTO SUPPLIERS LIMITED

Edwin Avenue,
Hoo Farm Industrial Estate,
Kidderminster, DY11 7RA,
Worcestershire. United Kingdom.

Tel: +44 (0) 1562 865577
Fax: +44 (0) 1562 865588

info@autosuppliers.co.uk
www.autosuppliers.co.uk

MAZDA REPLACEMENT PARTS 1/10/06

| AS. PART NO. | MAZDA PART NO. | DESCRIPTION |
|--------------|----------------|--|
| AS 16864 | 1661237 | Stabiliser Link Bar - 121 ('96-'00) |
| AS 17840 | 1175-99-324A | Tie Rod End - 929 ('74-81) |
| AS 17474 | 410077732 | Particle Filter - 121 |
| AS 17844 | 8531-99-322A | Inner Tie Rod - 323, 626 ('77-'87) |
| AS 17842 | 8531-99-356 | Lower Ball Joint - 323 ('77-'87) |
| AS 16991 | 8AG4-32-280 | Tie Rod End - 626 ('92-'97), MX-6 ('92-'98), Xedos 6 ('92-'99) |
| AS 14395 | A160-02-F3A1 | Cam Angle Sensor 'O' Ring |
| AS 17605 | B26R-28-170 | Front Suspension Link - 323 (98-'03) |
| AS 17604 | B26R-34-170 | Front Suspension Link - 323 (98-'03) |
| AS 17843 | B455-32-280 | Tie Rod End - 323 |
| AS 15619 | B455-34-46XA | Front Lower Arm Support L/H - 323 (1989-94) |
| AS 15618 | B455-34-46YA | Front Lower Arm Support R/H - 323 (1989-91) |
| AS 16990 | B455-34-550 | Lower Ball Joint - 323 ('89-'95) |
| AS 15617 | B459-34-470 | Front Lower Suspension Inner Bush - 323 (1991-95) |
| AS 14392 | B3C7-10-602A | Crankshaft Seal |
| AS 14514 | B25E-32-180 | Power Steering Rack Seal Kit - Protégé (1995) |
| AS 15403 | BAU1-15-171A | Thermostat (82 deg.) - MX5 / Miata / MX6 (86-92) |
| AS 15616 | BC1D-34-470 | Wishbone Bush - 323 (1989-94) |
| AS 15621 | BC1F-34-46X | Front Lower Arm Support R/H - 323 (1994-95) |
| AS 15620 | BC1F-34-46Y | Front Lower Arm Support L/H - 323 (1994-95) |
| AS 17000 | BC1O-28-170A | Rear Stabiliser Link - 323 ('92-'98) |
| AS 17615 | BJ25-32-12S | Thermoplastic Steering Rack Gaiter - 323 |
| AS 17841 | BO01-32-135 | Inner Tie Rod |
| AS 17010 | BO1A-34-300 | Control Arm R/H - 323 ('94-'98) |
| AS 17009 | BO1A-34-350 | Control Arm L/H - 323 ('94-'98) |
| AS 14394 | BP01-10-602A | Crankshaft Seal |
| AS 17957 | BP4K-34-170C | Front Suspension Link - 3 ('03 on), 5 ('05 on) |
| AS 17011 | DO31-34-320A | Track Control Arm - 121 ('88-'91) |
| AS 16120 | E301-40-305 | Exhaust Gasket - MX-5 1.6i 16v Cat. |
| AS 13990 | F001-22-540 | CV Boot Inner - Eunos |
| AS 13987 | F037-22-530 | CV Boot Outer - Eunos |
| AS 14393 | FS05-10-602A | Camshaft Seal |
| AS 13989 | G002-22-530 | CV Boot Inner - Eunos |
| AS 13986 | G026-22-540 | CV Boot Inner - Eunos |
| AS 16994 | G030-32-240A | Tie Rod R/H (Manual Steering) - 626 ('82-'87) |
| AS 16995 | G030-32-250A | Tie Rod L/H (Manual Steering) - 626 ('82-'87) |
| AS 16989 | G030-99-356 | Lower Ball Joint - 626 Mk2 ('82-'87) |
| AS 16996 | G037-32-240C | Tie Rod R/H (Power Steering) - 626 ('82-'87) |
| AS 16997 | G037-32-250C | Tie Rod L/H (Power Steering) - 626 ('82-'87) |
| AS 17004 | GA2A-34-46XA | Front Arm Support Mounting R/H - 626 ('92-'97) |

| | | |
|----------|--------------|--|
| AS 17003 | GA2A-34-46YA | Front Arm Support Mounting L/H - 626 ('92-'97) |
| AS 16993 | GA2A-32-240 | Tie Rod R/H - 626 ('92-'97), MX-6 ('92-'98), Xedos 6 ('92-'99) |
| AS 16992 | GA2A-32-250 | Tie Rod L/H - 626 ('92-'97), MX-6 ('92-'98), Xedos 6 ('92-'99) |
| AS 15614 | GA2A-34-150 | Front Stabiliser Link R/H - 626 (1991 on), 323 (1994 on) |
| AS 15615 | GA2A-34-170 | Front Stabiliser Link L/H - 626 (1991 on), 323 (1994 on) |
| AS 15622 | GA2A-34-470 | Front Suspension Bush - MX5 (1998 on) |
| AS 17002 | GA2B-34-470 | Front Wishbone Bush - 626 ('92-'97) |
| AS 16998 | GA2C-28-170A | Rear Stabiliser Link - 626 ('93 on) |
| AS 17008 | GA6BE-34-300 | Control Arm R/H - 626 ('92-'97), MX-6 ('91-'98) |
| AS 17007 | GA6BE-34-350 | Control Arm L/H - 626 ('92-'97), MX-6 ('91-'98) |
| AS 13991 | GE4T-32-12X | Steering Rack Gaiter (Thermoplastic) - Eunos |
| AS 17005 | GJ21-34-460 | Front Suspension Bush - 626 ('87-'92) |
| AS 17006 | KA10-34-470 | Front Suspension Bush - 626 2.2l ('90-'93) |
| AS 13988 | M090-22-540 | CV Boot Inner - MX5 / Eunos |
| AS 14396 | NA01-28-111 | Shock Absorber Boot - MX5 |
| AS 17616 | NA01-32-240 | Tie Rod End - MX-5 ('90-'99) |
| AS 11977 | NA02-32-180 | Power Steering Rack Seal Kit - MX5 (1990-95) |
| AS 13992 | NC10-32-125 | Steering Rack Gaiter (Thermoplastic) - MX5 |
| AS 14513 | NC10-32-180 | Power Steering Rack Seal Kit - Miata / MX5 (1999-2001) |
| AS 11499 | O3D5-40-081 | Exhaust Mounting - 929, RX-4 |
| AS 17141 | SA39-32-115 | Tie Rod - E2000, E2200 ('83 on) |
| AS17839 | UA01-32-220 | Pitman Arm RHD - B1800 ('82-'85) |
| AS 17838 | UA01-99-323 | Inner Tie Rod - B1800 ('82-'85) |
| AS 13704 | - | Power Steering Rack Seal Kit - MX5 (1996-97) |
| AS 15404 | - | Radiator Cap - MX6 |

NB. Manufacturers Names & Part Numbers are used for Reference Only.