

AUTO SUPPLIERS LIMITED

Edwin Avenue,
Hoo Farm Industrial Estate,
Kidderminster, DY11 7RA,
Worcestershire. United Kingdom.

Tel: +44 (0) 1562 865577
Fax: +44 (0) 1562 865588

info@autosuppliers.co.uk
www.autosuppliers.co.uk

LDV REPLACEMENT PARTS 1/10/06

AS. PART NO.	LDV PART NO.	DESCRIPTION
AS 16979	5044971	Drag Link RHT (GSJ180) - Sherpa ('74-'85), 200 series ('85
AS 16980	5044972	Drag Link RHT (GSJ181) - Sherpa ('74-'85), 200 series ('85
AS 16981	FBU7716	Drag Link (GSJ220) - Sherpa ('82-'89), 400 series ('89-'96), Convoy ('96 on)
AS 16982	FBU7717	Drag Link (GSJ221) - Sherpa ('82-'89), 400 series ('89-'96), Convoy ('96 on)
AS 16988	FBU7721	Drag Link R/H (GSJ833) - 200 series ('89-'96)
AS 16987	FBU7722	Drag Link L/H (GSJ832) - 200 series ('89-'96)
AS 16986	FBU7727	Outer Tie Rod End R/H (GSJ831) - 200 series ('89-'96)
AS 16985	FBU7728	Outer Tie Rod End L/H (GSJ830) - 200 series ('89-'96)
AS 16983	GSJ182	Outer Tie Rod End R/H - Sherpa ('74-'89), 200 series ('89-'9
AS 16984	GSJ183	Outer Tie Rod End L/H - Sherpa ('74-'89), 200 series ('89-'9
AS 14295	LBU6136/6146	Steering Box Repair Kit

NB. Manufacturers Names & Part Numbers are used for Reference Only.